## K S School of Engineering and Management

#15 MALLASANDRA, OFF, KANAKAPURA MAIN ROAD

Bangalore-560109

## Department of Civil Engineering

Date: 04th Jan 2019

To

Ambient constructions
Ph no: 7411008777

6 sets of 3 concrete cubes were sent for compressive strength test. In which 4 cubes were found of irregular shapes. The test was conducted and results are described as below.

Date of testing: 04th Jan 2019

|         | Cube no | Date of      | Weight | Max.   | Comp.    | Average  | Remarks   |
|---------|---------|--------------|--------|--------|----------|----------|-----------|
|         |         | Cast         | in Kg  | Load   | Strength | Strength |           |
|         |         |              |        | (kN)   | (N/mm2)  | (N/mm2)  |           |
|         | 1       | `            | 7.88   | 661.9  | 29.4     |          | 21 days   |
| Set I   | 2       | 12/12/2018   | 8.2    | 376.9  | 16.7     | 24.3     | strength  |
|         | 3       | ]            | 8.00   | 625.9  | 27.8     |          | M20       |
|         | 4       |              | 8.40   | -      | Ā        |          | Irregular |
|         |         | 19/12/2018   |        |        |          |          | shape     |
| Set II  | 5       | 1 [          | 8.10   | 419.3  | . 18.6   | -        |           |
| 50111   | 6       | 1 1          | 8.10   | 385    | 17.1     |          |           |
|         | 7       |              | 8.0    | 481.0  | 21.3     |          |           |
| Set III | 8       | 19/12/2018   | 8.1    | -      | -        | -        | trregular |
| 301 111 |         |              |        |        |          |          | shape     |
|         | 9       |              | 7.9    | 488.4  | 21.7     |          |           |
|         | 10      |              | 7.8    | -      | -        |          | Irregular |
| Set IV  | "       | 25/12/2018   |        |        |          | -        | shape     |
|         | 11      |              | 7.42   | 201.10 | 8.9      | _        |           |
|         | 12      | -{           | 7.6    | 203.3  | 9.00     |          |           |
|         |         |              | 8.0    | 344.7  | 15.3     |          |           |
|         | 13      | 21/12/2018   | 8.12   |        | -        |          | Irregular |
| Set V   | 14      | 21/12/2010   |        |        |          | -        | shape     |
|         |         | -            | 7.84   | 427.6  | 19.0     |          |           |
|         | 15      |              | 8.5    | 802.6  | 35.6     |          | 28 days   |
|         | 16      | 02/12/2018   |        | 773.1  | 34.3     | 35.5     | strengtl  |
| Set VI  | 17      | - 02/12/2018 | 8.77   | 829.4  | 36.8     |          | M30       |
|         | 18      |              | 0.77   |        |          |          |           |

Regued Report

Head of Department
Professor & Head
Dept. of Civil Engineering
K.S. Group of Institutions
K.S. School of Engineering & Management Bangalore-560 062.

## K S School of Engineering and Management

#15 MALLASANDRA, OFF, KANAKAPURA MAIN ROAD

Bangalore-560109

## Department of Civil Engineering

Date: 04th Jan 2019

To

Ambient constructions Ph no: 7411008777

| Sl.no | Date of Testing | No of Cubes | Rate (Rs) | Amount (Rs) |
|-------|-----------------|-------------|-----------|-------------|
| 1.    | 04/01/2019      | 18          | 50        | 900         |
|       |                 | 900         |           |             |

Amount to be paid in words is Nine hundred rupees only

Head of Department

Wille

Professor & Head Dept. of Civil Engineering K.S. Group of Institutions K.S. School of Engineering & Manager Bangalore-560 062.

For additional information: View Document